

Hiller UH12B S/N 613 N5072R					Hobbs		0.0
					Total Time Airframe		3083.6
Component Name	Part No.	Serial No.	Overhaul Schedule	Installed@Aircraft Total Time	Time on Component@Install	Overhaul@A/C Total Time	Hours Remaining
Hobbs Meter (Datcon)	100690		N/A	3083.6	0.0	N/A	N/A
Engine	6V350A	40012	1200.0	3083.6	0.0	4283.6	1200.0
Main Transmission	23400-6M	2774	900.0	3083.6	0.0	3983.6	900.0
Tail Rotor Gearbox	25035-5	760	900.0	3083.6	0.0	3983.6	900.0
Main Rotor Head Assembly	51437-7	3145	900.0	3083.6	0.0	3983.6	900.0
Main Rotor Blade	40-001-5	2163	On Condition	3083.6	0.0	On Condition	On Condition
Main Rotor Blade	40-001-5	2164	On Condition	3083.6	0.0	On Condition	On Condition
Control Rotors	36123	N/A	1200.0	3083.6	0.0	4283.6	1200.0
Tail Rotor Assy	55067	N/A	600.0	3083.6	0.0	3683.6	600.0
Fan Drive Gear Box	1418-1	1220	900.0	3083.6	0.0	3983.6	900.0
Engine Controls	3A1630	N/A	1800.0	3083.6	0.0	4883.6	1800.0
Collective & Cyclic Pitch Controls	30003	N/A	1800.0	3083.6	0.0	4883.6	1800.0
Engine Mount Frames&Snubbers	63107	N/A	1800.0	3083.6	0.0	4883.6	1800.0
Starter	1109662	1118	@Engine Overhaul	3083.6	0.0	4283.6	1200.0
Generator	8MR3404G	110-684	@Engine Overhaul	3083.6	0.0	4283.6	1200.0
Oil Cooler & Regulator	FAP16AN09-0AM	FF-32	@Engine Overhaul	3083.6	0.0	4283.6	1200.0
Engine Driven Fuel Pump	6005-2	20655	@Engine Overhaul	3083.6	0.0	4283.6	1200.0
Skid Gear	43006-1	N/A	@Engine Overhaul	3083.6	0.0	4283.6	1200.0
Clutch Housing Assembly	21001-1	N/A	1200.0	3083.6	0.0	4283.6	1200.0
Fuel Shut Off Valve	N/A	N/A	1200.0	3083.6	0.0	4283.6	1200.0
Auxiliary Fuel Pump	N/A	N/A	On Condition	3083.6	0.0	On Condition	On Condition
Trim Motors	S21AE	N/A	2400.0	3083.6	0.0	5483.6	2400.0
Fuel Quantity Transmitter	81425-1	N/A	1200.0	3083.6	0.0	4283.6	1200.0



Tulsa Rotor Blades

The Hiller Wood Main Rotor Blades

Tulsa Rotor Blades uses some of the original equipment to repair your blades
and can do the smallest repairs to a complete rebuild.

Complete repair includes new retention plates, retention plate straps, trim tabs, stainless leading edges, and fabric.

Rotor blade sets are balanced to factory specifications.

Custom paint jobs for higher visibility on request.

Exchange your set for one of ours to get you back in the air sooner.



Price on a Complete Repair is set at \$18,500.00 USD.

Right now TRB has one set for sale at \$25,500.00 USD.

Exchange your repairable blade set for \$19,500.00 USD.

Root end repairs. From root to stainless leading edge. Both blades \$8,500.00

Includes new retention plates, retention plate straps, and balancing.

Change Leading Edge Stainless. Both blades \$8,500.00

Includes balancing.

Fabric change. Includes balancing. \$7,000.00

Trim tab One blade \$650.00

Both blades \$1,000.00

These prices are estimates and subject to change according to the needs of repair.

Tulsa Rotor Blades



P.O. Box 471603
Tulsa, Oklahoma, 74147
Phone: 918-693-0336



<http://www.TulsaRotorBlades.com>

Name:				Work Order #:	22 006	
Tom Valinti				Date In:	9/07/2022	
Address:	23902 127th. Ave. NE			Date Out:	03/28/2023	
City:	Arlington	WA	98223	Todays Date:	03/29/2023	
Phone:	Fax:				Customer Order #:	verbal
Blade Part#:	40-001-5	Blade Set#:	P2163H	P2164H	Labor charge	

REPAIR ORDER INSTRUCTIONS

Overhaul, paint, and balance

Repair 56' of spar due to cut outs.

Replace tips caps.

PAID IN FULL: March 28, 2023

WT

Hours @ \$55.00 per hour

Outside repairs

X Customer signature When applicable

Total labor

Mechanic's signature When applicable

Total parts

Mechanic's signature When applicable

Sub total


Freight

Tax

Total Amount

\$22,500.00

Tulsa Rotor Blades



P.O. Box 471603
Tulsa, Oklahoma, 74147
Phone: 918-693-0336



<http://www.TulsaRotorBlades.com>

Tom. Valenti
 23902127th Ave, NE
 Arlington, Wash. [98223]

971 412 5235
 murdockak@yahoo.com

9950 NW Rex Brown Rd
 Carlton, OR 97111

Date:06/23/2023

Project: N5072R maintenance items

Invoice No. 230623N5072R

Terms: upon receipt

Description	Quantity	Unit Price	Cost
Mobilization cost	300	\$0.66	\$198.00
N5072R align/check 1" tail rotor drive shaft	2	\$105.00	\$210.00
N5072R remove magnetos for repair	0.5	\$105.00	\$52.50
N5072R remove and re install mag drives time magnetos to engine	3	\$105.00	\$315.00
N5072R replace mag drive seals	2.5	\$105.00	\$262.50
N5072R replace o rings in fuel pump(eng. driven)	1	\$105.00	\$105.00
Magneto drive seals CR 4990	2	\$12.00	\$24.00
Ground run/check aircraft/engine for proper operation	1	\$105.00	\$105.00
Total		Worthless things	\$1,272.00

Make check payable to :Karson-M: Branham.

Thank you for your business. It's our aim to provide the best technical service on planet earth.

Sincerely yours,

Karson

United States of America

Department of Transportation—Federal Aviation Administration

EA-2-9

Supplemental Type Certificate

Number SU446EA

This certificate, issued to Franklin Engine Company, Inc.
Liverpool Road
Syracuse, New York 13208.

certifies that the change in the type design for the following product with the limitations and conditions
hereinafter specified herein meets the airworthiness requirements of Part 6 of the Civil Air
Regulations.

Original Product—Type Certificate Number: 6H1, 6H2
Manufacturer: Fairchild - Hiller
Model: UH-12A, UH-12B, UH-12C

Description of Type Design Change:

Installation of Franklin Engine Model 6V-350B in Fairchild - Hiller UH-12B or
UH-12C helicopter in accordance with Franklin Engine Company, Inc. Service
Instruction No. 16 dated 21 March 1966.

Installation of Franklin Engine Model 6V-350B in Fairchild - Hiller UH-12A
helicopter in accordance with Carson Helicopters Inc. Service Instruction No. 29
dated 23 April 1970.

Limitations and Conditions:

For Hiller UH-12B and UH-12C models, Franklin Engine Co. Inc. Helicopter Flight
Manual Supplement No. 1, FAA approved 11/7/66 is required.

For Hiller UH-12A model, Franklin Engine Co. Inc. Helicopter Flight Manual
Supplement No. 1, FAA approved 11/7/66, Revised 30 June 1970 is required.

This certificate and the supporting data which is the basis for approval shall remain in effect until sur-
rendered, suspended, revoked, or a termination date is otherwise established by the Administrator of the

Federal Aviation Administration.

Date of application: 21 March 1966

Date issued:

Date of issuance: 7 November 1966

Date recorded: 30 June 1970



By original of the Administrator
W. Oleksak

(Signature)

W. V. NORTON
Chief, Engineering & Manufacturing Br.

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.
This certificate may be transferred in accordance with FAR 21.47.

Supplemental Type Certificate

Number SH277WE

This certificate, issued to

PENLAND HELICOPTER REPAIR, Inc.
P. O. BOX 1838
Porterville, California 93258

certifies that the change in the type design for the following product with the limitations and conditions
therefor as specified hereon meets the airworthiness requirements of Part 6 of the Civil Air
Regulations.

Original Product—Type Certificate Number: 6H2
Make: Hiller
Model: UH-12B Normal Category

Description of Type Design Change: Installation of UH-12C Upper Canopy in
accordance with Helicopter Repair Service, Inc. Installation Instructions HRSI
1002, dated November 17, 1980.

Helicopter Repair Service, Inc. FAA Approved RFM Supplement dated December 10,
1980, is required.

Limitations and Conditions: The approval of this change in type design applies to
Hiller UH-12B airplanes only. This approval should not be extended to other
aircraft of this model on which other previously approved modifications are
incorporated unless it is determined by the installer that the
interrelationship between this change and any of those other previously approved
modifications will introduce no adverse effect upon the airworthiness of that
aircraft.

This certificate and the supporting data which is the basis for approval shall remain in effect until sur-
rendered, suspended, revoked, or a termination date is otherwise established by the Administrator of the
Federal Aviation Administration.

Date of application: May 27, 1980

Date issued: June 8, 1994

Date of issuance: December 10, 1980

Date amended:

By direction of the Administrator


Nelson Schartier
(Signature)

Manager, Technical & Administrative
Support Staff

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.

This certificate may be transferred in accordance with FAR 21.47.

09/28/2006 21:42 9413781704

FROM: HILLER AIRCRAFT

DTAMPW

PHONE NO.: 408 384 3100

MP: 07 1396 01:00PM P1

HILLER AIRCRAFT



April 7, 1998

FACSIMILE

TO: RICK SHARP

FAX: 713-649-8136

SUBJECT: ALTERNATE FUEL PUMP UH-12 B/LC

The Facett Fuel Pump P/N 476-411 approved on STC SH46WE is an acceptable alternate for the original factory installed component.

STC SH46WE is to be used as the basis for approval. Replacement fuel lines must be of equal capacity to the original and installed in a similar manner. Fuel pressure must be adjusted to that found in the limitations section of the Rotorcraft Flight Manual.

The Facett pump meets the requirement of Hiller Dwg. 72157, Note 17, which requires a Weldon Commercial Pump P/N 4013 or Equivalent.

Sincerely,

Nick Parkinson
Project EngineerNP/st
npx37.98

Dawn P/N 476088

AIRCRAFT SERVICE
1-877-477-7823

ASCPS

HILLER AIRCRAFT



August 13, 1999

Sid Evans
5870 Dove St.
Sarasota, FL 34241

Subject: HILLER SERVICE BULLETIN 69 - "INSTALLATION OF 50 AMPERE GENERATOR"

Dear Sir.

The subject Bulletin was introduced in 1958 to provide means to drive a generator of increased capacity when compared to the existing engine driven component.

The drive system and associated structure was designed for use with a Eclipse-Pioneer No. 30B24-1 generator, modified by Hiller in accordance with drawing 76210.

Hiller has no technical objection to the use of an alternator in place of the generator as long as the following conditions are complied with:

- The alternator is lighter than the unit it is replacing.
- The alternator shaft incorporates a shear section that will separate if the alternator bearings seize.
- The drive load is no greater than required by the existing unit. (Alternator output less than 50 amps.)

Wiring changes should be in accordance with standard practices and the requirements of the alternator and control unit.

These precautions were all addressed when Hiller certified a similar alternator for generator installation for the later UH-12D and E models. (Ref. Hiller S.B. UH-12-83-3).

Yours Sincerely,

Nick Parkinson
NRP/st
Enclosures
scvns

INVOICE

Tom. Valenti

23902127th Ave, NE

Arlington, Wash. [98223]

971 412 5235

murdockak@yahoo.com

9950 NW Rex Brown Rd

Carlton, OR 97111

Date:07/02/2023

Project: N5072R maintenance items

Invoice No. 020723N5072R

Terms: upon receipt

Description	Quantity	Unit Price	Cost
mobilization	1	\$38.75	\$38.75
perform cyl compression check on engine	1	\$105.00	\$105.00
clean inspect, test and reinstall spark plugs	2	\$105.00	\$210.00
test/check all spark plug leads	0.5	\$105.00	\$52.50
check/adjust magneto timing	1	\$105.00	\$105.00
Ground run/check aircraft/engine for proper operation	0.75	\$105.00	\$78.75
Total		Worthless things	\$590.00

Make check payable to :Karson-M: Branham.

Thank you for your business. It's our aim to provide the best technical service on planet earth.

Sincerely yours,

Karson

971 412 5250

murdockak@yahoo.com

9950 NW Rex Brown Rd

Carlton, OR 97111

Date:07/21/2023

Project: N5072R maintenance items

Invoice No. 210723N5072R

Terms: upon receipt

Description	Quantity	Unit Price	Cost
mobilization	550	\$0.66	\$363.00
Remove transmission, replace crankshaft seal and transmission input seal, reassemble aircraft from parts removed for seal change, clutch inspection performed. (Daily rate)	2	\$950.00	\$1,900.00
Technical consult	2	\$100.00	\$200.00
Crankshaft oil seal 415295	1	\$55.00	\$55.00
Transmission input shaft seal 472015	1	\$30.00	\$30.00
Shop consumables	1	\$50.00	\$50.00
Motel	2	\$120.00	\$240.00
AN5H5A Bolt	1	\$8.00	\$8.00
Total		Worthless things	\$2,846.00

Make check payable to :Karson-M: Branham.

Thank you for your business. It's our aim to provide the best technical service on planet earth.

Sincerely yours,

Karson

VELOCITY SHOPPE
724 BRITTON RD. N.E.
EL RENO, OK. 73036
405-413-4972

WORK ORDER
488021

CUSTOMER'S ORDER NO.	DEPARTMENT	DATE					
	977090	6-19-23					
NAME	TOM VALENTI						
ADDRESS	23902 127 TH AVE NE						
CITY, STATE, ZIP	ARLINGTON WA 98223						
SOLD BY	CASH	C.O.D.	CHARGE	ON. ACCT.	MDSE. RETD.	PAID OUT	
10-52350-2	SN 289156				SGRN-23		
QUANTITY	DESCRIPTION	PRICE	AMOUNT				
1	1 2-202 BEARING	94.50					
2	1 10-92815-37 RETAINER	5.50					
3	1 10-160844 BRUSH	14.50					
4	1 10-357173 BREAKER ASSY	124.50					
5	1 10-400554 SEAL	38.50					
6	1 10-90751-18 COTTER KEY PARTS	3.50					
7		281.50					
8							
9	REPAIR MAG REPLACING						
10	LISTED PARTS - RUN ON						
11	TEST BENCH AS PER						
12	I.A.W. TCM X42002-1 MANUAL	185.50					
13	TOTAL	466.50					
14							
15							
16							
17							
18							
RECEIVED BY							

KEEP THIS SLIP FOR REFERENCE

VELOCITY SHOPPE
724 BRITTON RD. N.E.
EL RENO, OK. 73036
405-413-4972

WORK ORDER
488020

CUSTOMER'S ORDER NO.	DEPARTMENT	DATE					
	977090	6-19-23					
NAME	TOM VALINTI						
ADDRESS	23902 127 TH AVE NE						
CITY, STATE, ZIP	ARLINGTON WA 98223						
SOLD BY	CASH	C.O.D.	CHARGE	ON. ACCT.	MDSE. RETD.	PAID OUT	
10-52350-2	SN 282202				SGRN-23		
QUANTITY	DESCRIPTION	PRICE	AMOUNT				
1	10-81806 BEARING	89.50					
2	1 2-202 BEARING	94.50					
3	1 10-92815-37 RETAINER	5.50					
4	1 10-160844 BRUSH	14.50					
5	1 10-357173 BREAKER ASSY	124.50					
6	1 10-400554 SEAL	38.50					
7	1 10-90751-18 COTTER PIN PARTS	3.50					
8		370.50					
9							
10	REPAIR MAG REPLACING						
11	LISTED PARTS - TEST RUN						
12	ON TEST BENCH AS PER						
13	I.A.W TCM X42002-1 MANUAL	185.50					
14	TOTAL	556.00					
15							
16							
17							
18							
RECEIVED BY							

KEEP THIS SLIP FOR REFERENCE


VELOCITY SHOPPE
724 BRITTON RD. N.E.
EL RENO, OK. 73036
405-413-4972

WORK ORDER
488047

CUSTOMER'S ORDER NO.	DEPARTMENT	DATE				
	776560	9-3-23				
NAME	TOM VALINTI					
ADDRESS	23902 122 TH AVE NE					
CITY, STATE, ZIP	ARLINGTON WA 98223					
SOLD BY	CASH	C.O.D.	CHARGE	ON. ACCT.	MDSE. RETD.	
10-4809	9W	BC-16-644			MA4-5	
QUANTITY	DESCRIPTION			PRICE	AMOUNT	
1	2	15-A21	SCREW	5.50	11 00	
2	2	15-A23	SCREWS	4.50	9 00	
3	1	16-6725	GASKET SET		117 50	
4	1	24-A30	SPRING		5 50	
5	2	82-11	COTTER PINS	3.50	7 00	
6	1	82-1	COTTER PIN	"	3 50	
7	1	229-585	IDEE TUBE	CUSTOMER FURNISHED		
8	1	242-528	MIX VALUE		128 50	
9	1	66224	GASKET		5 50	
10	1	652158	GASKET		6 50	
11			PARTS		294 00	
12						
13	REPAIRING & REPLACING					
14	LISTED PARTS - FLOAT LEVEL					
15	SET AS PER MARVEL MAGAFSM					
16	MANUAL					
17	TOTAL					185 50
18						466 50

RECEIVED BY

HILLER HELICOPTERS



ILLUSTRATED
PARTS BREAKDOWN LISTS
FOR
HILLER MODEL
UH-12A*
and
UH-12B**
Helicopters

- ***H-12A Use information contained herein for Model H-23A, except for the Cyclic Floor Stick Inst. and 24 volt Electricl System.
- ***H-12B Use information contained herein for Model H-23B.

HILLER HELICOPTERS
HELICOPTER MODEL
HILLER 300
(CH-12B)
N-274
EQUIPPED W.I.B. SWING GEAR
OR FOXTE-MARSH GEAR

HELICOPTERS
FLIGHT MANUAL

This Document Must be Carried In
The Aircraft at all Times

TYPE CERTIFICATE
NO. 682

REGISTRATION NO.

Approved by: Morton J. Brown C.R.A.
CHIEF, AIRCRAFT ENGINEERING BRANCH

Date of Approval: March 27, 1952

Hiller Helicopters, Palo Alto, California

TM 1-1H-23A-1

DEPARTMENT OF THE ARMY TECHNICAL MANUAL

FLIGHT HANDBOOK
ARMY MODELS H-23A
B, ASD C HELICOPTERS

"NOT LIABLE FOR ACCURACY
AND EFFECTIVENESS OF
ORIGINAL TEXT."

Air Service Caravan Co., Inc.

Note. This manual replaces AF TO 1H-23A-1, 15 January 1958, for
use within the Department of the Army.

This manual supersedes TM 1-1H-23A-1, 10 August 1956.

"NOT LIABLE FOR ACCURACY
AND EFFECTIVENESS OF
ORIGINAL TEXT."
Air Service Caravan Co., Inc.



HEADQUARTERS, DEPARTMENT OF THE ARMY
APRIL 1958

NOTICE

Weight and balance or operating limitation changes shall be entered in the appropriate aircraft record. An alteration must be compatible with all previous alterations to assure continued conformity with the applicable airworthiness requirements.

8. Description of Work Accomplished
(If more space is required, attach additional sheets. Identify with aircraft nationality and registration mark and date work completed.)

USA N8109H

October 8, 2014

Nationality and Registration Mark

Date

The following modification of the helicopter UH-12A was completed at an unknown date and by persons unknown as previous logbooks are not available. I have inspected and verify the absence of a Weldon Aux Electrical fuel pump P/N 4013 Serial number N/A from the fuel strainer bracket located at 78 inches at #3 and the installation of a Facet Aux Electric Fuel Pump P/N 476-411 located at 78 inches at #3 I.A.W. Hiller MIM and Far 43.2. I verify this change was done in accordance with STC SH46WE and is an acceptable alternate for the original factory installed component. Replacement fuel lines are of equal capacity to the original and installed in a similar manner. Fuel pressure is adjusted to that found in the limitations section of the Rotorcraft Flight Manual. The Facett pump meets the requirement of Hiller Dwg. 72157, note 17, which requires a Weldon Commercial Pump P/N 4013 or equivalent. Ground and flight check is normal. Weight and balance is not affected. I have made an appropriate note in the present logbook to that effect. In addition a supplemental notation was installed in the Flight Manual.

-end-

TO: STEVE

THREE hours to SPOT transmission case and INSTALLED
New HULL DOWN STUD THAT WAS BROKEN RE SEEDS TX

3 HRS \$240.00

SPARE PARTS

1.	COOLING FAN GEAR BOX overhauled	\$ 560.00
2.	" " COUPLER (new)	49.00
3.	ELECT FUEL PUMP (new)	109.00
4.	ENGINE DRIVEN FUEL PUMP	290.00
5.	New AIR FILTER	39.00

TOTAL DUE

\$1,238.00