



F-28F/280F COMPONENT RETIREMENT LIFE STATUS

2,350 POUNDS OR 2,600 POUNDS MAX GROSS WEIGHT

| REGISTRATION # | N280SH | SERIAL NUMBER | 2095 | ANNUAL DUE: | 3/31/2020 | | |
|-----------------------------------|----------------|---------------------------|----------------------------------|------------------------------|---------------------------------------|---|--|
| AIRCRAFT T.T. | 734 | ENGINE T.T. | 734 | DATE | 9/6/2019 | | |
| PART/COMPONENT DESCRIPTION | PART NUMBER | PART/COMPONENT TOTAL TIME | PART/COMPONENT SERVICE LIFE | PART/COMPONENT SERIAL NUMBER | PART/COMPONENT INSTALLED AT ACFT T.T. | PART/COMPONENT REPLACEMENT DUE AT ACFT T.T. (HOBBS + 215) | |
| MAIN ROTOR BLADE ASSEMBLY | 28-14100-9 | 734 | 95,000 | 5264U-B | 0 | 95,000.00 | |
| MAIN ROTOR BLADE ASSEMBLY | 28-14100-9 | 734 | 95,000 | 5266U-B | 0 | 95,000.00 | |
| MAIN ROTOR BLADE ASSEMBLY | 28-14100-9 | 734 | 95,000 | 5267U-B | 0 | 95,000.00 | |
| T T STRAP ASSEMBLY | AA-ECD-084-280 | 25.4 | 5 YRS | EB-10523 | 708.6 | JAN 2024 | |
| T T STRAP ASSEMBLY | AA-ECD-084-280 | 25.4 | 5 YRS | EB-10524 | 708.6 | JAN 2024 | |
| T T STRAP ASSEMBLY | AA-ECD-084-280 | 25.4 | 5 YRS | EB-10525 | 708.6 | JAN 2024 | |
| TACH DRIVE O RING | NAS 1611-33 | 25.4 | 5 YRS FROM INSTALL OR 8 YRS CURE | N/A | 708.6 | MAR 2024 | |
| IDLER BEARING | ECD018-11 | 167.4 | 600 | 14149-05 | 566.6 | 1166.6 | |
| IDLER BEARING | ECD018-11 | 167.4 | 600 | 14149-09 | 566.6 | 1166.6 | |
| MAIN ROTOR GEARBOX | 28-13170-103 | 734 | O/H @ 1,200 HRS | 78-012-98T | 0 | 1200 | |
| MAIN ROTOR SHAFT | 28-13140-11 | 734 | O/H ON CONDITION | 9-25-98-097CW | 0 | N/A | |
| LOWER SWASHPLATE YOKE | 28-16119-3 | 734 | 17,700 | 17-0115-99H | 0 | 17,700 | |
| CLUTCH | 28-13401-4 | 734 | O/H @ 2,400 | 295 | 0 | 2,400.00 | |
| MAIN ROTOR DRAG LINK | 28-14283-1 | 734 | 13,750 | 12211-01 | 0 | 13,750 | |
| MAIN ROTOR DRAG LINK | 28-14283-1 | 734 | 13,750 | 02211-18 | 0 | 13,750 | |
| MAIN ROTOR DRAG LINK | 28-14283-1 | 734 | 13,750 | 02211-20 | 0 | 13,750 | |
| TAIL ROTOR GEARBOX ASSEMBLY | 28-13525-5-R | 734 | O/H @ 1,200 HRS | 03-227-83T | 0 | 2,164 | |
| TAIL ROTOR GEARS | ECD100-1A-2 | 734 | 1,200 | 588-02AC | 0 | 2,164 | |
| SPINDLE, TAIL ROTOR ASSEMBLY | 28-150074-11 | 734 | 1,200 | 02-015-92ST | 0 | 1,764 | |
| 7 PLATE FLEX PACKS | 28-01041-3 | 360 | 1,200 | N/A | 374 | 1,827 | |
| 7 PLATE FLEX PACKS | 28-10141-3 | 360 | 1,200 | N/A | 374 | 1,827 | |
| TAIL ROTOR BLADE | 28-150002-1 | 734 | 3,100 | 2693 | 0 | 3,707 | |
| GRIP, TAIL ROTOR BLADE | 28-150044-1 | 734 | 6,200 | 2693 | 0 | 6,807 | |
| TAIL ROTOR BLADE | 28-150002-1 | 734 | 3,100 | 2694 | 0 | 3,664 | |
| GRIP, TAIL ROTOR BLADE | 28-150044-1 | 734 | 6,200 | 2694 | 0 | 3,254 | |
| TURBOCHARGER | 3BT5EE10J2 | 366 | OVERHAUL @ 1,000 RETIRE @ 2,000* | H-TS1213021 | 652 | 1,284.00 | |
| OTHER REQUIRED INSPECTIONS | | | | | | | |
| TRANSPONDER 91.413 | | | TEST 2 YEARS | | | Mar-21 | |